

# Case Study

## White Friars Housing Group Ltd Vincent Wyles & William Malcolm Building Survey



#### **Client Brief**

To provide an inspection team to carry out a detailed inspection of the façade of Vincent Wyles House and William Malcolm House residential tower blocks.



#### **Our Solution**

Arco Professional Safety Services Ltd provided an IRATA qualified examination team to carry out a detailed (tactile) examination of Vincent Wyles House and William Malcolm House residential tower blocks on a 6 monthly basis over a two year period.

Our team Removed/stabilised any loose materials identified during the survey and provided a detailed report of the findings.



### **Benefit of our Solution**

Our inspection team could get within touching distance of the Façade to thoroughly inspect it and remove any loose material making it safe for the public below



